

Downstacker AC Conveyor Drive Upgrade

Upgrade

Upgrade Application

A new belt conveyor AC drive is required to replace the old drive and to provide a more efficient and reliable drive.

Upgrade Description

The new drive will be a 100 HP AC drive with a 100 HP motor and a 100 HP inverter. The drive will be installed in the existing drive enclosure.

Upgrade Benefits

The new drive will provide a more efficient and reliable drive.

OEM's new drive will provide a more efficient and reliable drive.

Manufacturer's new drive will provide a more efficient and reliable drive.

Customer's new drive will provide a more efficient and reliable drive.

AC Drive Technology



The new drive will provide a more efficient and reliable drive.

Factory Talk Team One

Free Rockwell Automation's FactoryTalk Team One APP

Available for download on the Rockwell Automation website

Use the app to monitor and control the drive



Rockwell
Automation

PowerFlex
Communications